# HUD 203(k) Work Write-Up Consultant's Report

Prepared By

### **Early Home Inspection LLC**

1121 Chipping Court
Virginia Beach, VA 23455
(757) 478-1280
Tim, Paul or Brad @EarlyHomeInspection.com



# Inspection Date 3/3/2017

Client's Name: Jane Doe

**Inspected Address: 123 main Street** 

Anywhere, State 11111

Client's Phone: (757) 555-1212

**Client's Email:** 

JDoe123@email.com

**Lender: Sample Home Mortgage** 

Address: 5555 Any Street

Any Town, USA 55555

Phone: (222) 222-2222

**Loan Officer:** 

Phone: Ext:



<u>Date</u> 3/3/2017

# **Package Content Outline**

Lender: Sample Home Mortgage		Loan Officer:	Loan Type: HUD 203(k)									
Applicant's Name(s) Jane Doe  Applicant's Address 123 Main St, Anywhere, State USA 11111  Property Address 123 Main St, Anywhere, State USA 11111		Applicant's Phone (757) 555-1212  Work Phone  Cell Phone  Email JDoe123@email.com	Property Picture									
Other Contact	Contact's P	<u>'hone</u>	<u>Loan Number</u>									
Property Summary Information & Recommendations												
No. of Draws Requested: 3  Number of Units At Inspection: 1  Number Of Units At Completion: 0  Number of Dwellings: 0  Number of Stories: 3  Underground Oil Tank Certification Need  Utilities On At Time Of Inspection  Lead Paint Certification Need  Water Certification Need  Septic Certification Need  Septic Municipal Availability Prese	Draw Fe	es Recommended Per Draw:  Months To Completion: 2  Lot Size:  ding Size:  Recommendations  "Check Mark Indicates Yes'  moke Detectors Needed:   Asbestos Report Neeed:	\$350.00 Total Repair Estimate: \$28,150.00  Contingency Reserve: \$2,815.00 at 10%  Type of Construction: Masonry  Estimated Age: 100+  Termite - Woodboring Treatment Needed:									
FHA 203(k) Consultants Agreement:  Specification of Repairs:  Initial Draw Request:  Consultant's Invoice:  Narrative:  Work Write Up Totals:  Owners/Contractors Agreement:  Identity Of Interests:		Inis Package Cont  Inimum Property Standards:  orrowers Acknowledgement:  Private Well Report:  Radon Test Report:  Floor Layout Diagram:  Permit Certification Form;	Seperate Heating Certification:  Seperate Plumbing Certification:  Separate Electrical Certification:  Underground Oil Tank Certification:  Separate Structural Engineer Report:  Lead Paint Recommend Form:									
Certification Letter:	✓	Self Help Agreement:	Woodboring-Termite Report:									



Property Address	Consultant's File Number: 01 Sample Report					
123 Main St, Anywhere, State USA 11111	Inspection Date:         3/3/2017           Inspector:         Tim Early P-1882					
Applicant's Information	Picture					
Jane Doe  Address:t  123 Main St, Anywhere, State USA 11111  Home Phone:(757)						
Lender Information	Details					
Lending Institution: Sample Home Mortgage  Lender Loan #:	Number of Units  At Start:1					
Origination Date:  Loan Type: HUD 203(k)	Habitation / Occupancy: Occupied  ✓ Owner Occupied Investor/Builder					
Loan Originator:Ext:	<b>HUD Information</b>					
Contingency Reserve %:10%_ Number of Draws:3  Contractors On Project	FHA Case No.: HUD Date Assigned:					
,						

**Property Address** 

123 Main St, Anywhere, State USA 11111

Consultant's File Number: 01 Sample Report

Inspection Date:

3/3/2017

Inspector:

Tim Early P-1882

### **Initial Inspection Information**

	Inspect	tion Weather Conditions										
		Building Physica	al Informatio	on								
	Lot Size	Number of Dwellings	0	Type of Construction	Masonry							
	Building Size	Number of Stories	3	Estimated Age	100+							
	Commercial Units											
	Number of Commercial Units (	)	Utilities At Inspection									
	Commercial Units Ratio		#	Electric Services 1	On 🗸							
	Smoke Detectors			# of Gas Services0	On 🗌							
			Wat	ter Private	On 🗹							
	Smoke Detectors at Inspection  Type Required		Type O	f Sewer Public								
	Type Required											
Recommendations "Check Mark Indicates Yes"												
	Underground Oil Tank Certification	Needed:	-	Termite - Woodboring Treatme	ent Needed:							
	Utilities On At Time Of In	spection:	Radon Gas Test Preformed:									
	Lead Paint Certification	Needed:	Seperate Plumbing Certification Recommened:									
	Water Certification	Needed:	Seperate Electrical Certification Recommened:									
	Septic Certification	Needed:	Seperate Heating Certification Recommened:									
	Septic Municipal Availability	Present:	Seperate Structural Engineers Report Recommened:									
	Smoke Detectors	s Needed:		Asbestos Rep	port Neeed:							
comply very the construction that the constr		Standards as defined PERFORMED ACCORT BE VIEWED AS AN AL SERVICES MAY B mended inspections to	in HUD H RDING TO Y FORM E BENEF o further p	andbook 4905.1. Unless of the STANDARDS OF I OF CERTIFICATION BY ICIAL FOR THE BORRO protect their interests beyon	otherwise indicated by PRACTICE OF A A LICENSED WER. The borrower and scope of the							
-	Tim Earlyl											

# **Property Contractor List**

Contractor	Address	Phone	Work Preformed



# **Consultant's Summary**

#### **Property Summary**

Jane Doe 123 Main St, Anywhere, State USA 11111 (757) 555-1212

#### **Consultant's Summary**

X			Date:	3 <b>/3/201</b> 7	
Consultant's Signature	ID No.:	<b>P</b> 1882			



Inspection Date: 3/3/2017	Occupied During Construction:	Occupied	Months To Completion:	2
Borrower: Jane Doe	FHA Case #:			

**Specification Of Repairs** 

Property
Address:
Phone:
Contact Name:
Contact Phone:
Applicant's Phone:
Applicant's Cell Phone:

FHA Case #:

Loan Type: HUD 203(k)

Loan No.

Lender: Sample Home Mortgage

Lender's 5555 Any Street
Address: Any Town, USA 55555

Loan Originator:

Loan Originator Phone:

Sample Home Mortgage 5555 Any Street Any Town, USA 55555 FHA Case # Consultant's File No.

01 Sample Report

<u>Dated</u>

#### STEP-BY-STEP PROCEDURE

- 1. HUD accepted consultant who prepares this work write-up (or an architect, engineer or home inspection service) needs to inspect the property to assure: (1) That there are no rodents, termites and other infestations: (2) that there are no defects that will affect the health and safety of the occupants: (3) the adequacy of the existing structural, heating, plumbing electrical and roofing system: and (4) the upgrading of thermal protection (where necessary). The inspection report will be attached to the document.
- 2. Complete each item below as necessary by either filling out the information on the work to be preformed with a brief explanation, or entering "NONE" in the "SUB-TOTAL" Portion if no work is being performed in that particular subsection to the document.
- 3. The proposed work, and the materials used, should be explained in detail to assure a complete understanding on the required work by the contractor and the HUD authorized fee inspector. For major items (ie. kitchen cabinets, appliances, heating air conditioning etc.), the description or the item should enclose the make and model number (manufacturer's) brochure can be attached).
- 4. Attach a copy of any proposals from all contractors and/or subcontractors.
- 5. Provide other drawings as necessary to assure a complete understanding of the required work by the contractor and the HUD authorized fee inspector. The following architectural exhibits are required:
  - a) A Plot Plan of the Site is required only if a new addition is being made to the existing structure. Show the location elevations at the property corners and building structure(s), walks, drives, streets, and other relevant detail. Include finished grade corners to assure proper drainage of water off the site. Show the required flood elevation.
  - b) Proposed Interior Plan of the Dwelling. Show where structural or planning changes are contemplated; include any dwelling.
  - c) Provide kitchen cabinet elevations, deck drawings and other exhibits as necessary to properly describe the required Architectural exhibits for a new addition are the same as for a newly constructed home.
- 6. Cost estimates must include labor and materials sufficient to complete the work by a contractor.
- 7. A homebuyer who would like to do any of the work must submit a letter to the lender stating his/her qualifications to perform the work in timely and workmanlike manner. If approved by the lender, the homebuyer cannot eliminate the cost estimate for labor because if the homebuyer cannot complete the work there must be sufficient money in the escrow account to get a subcontractor to do the work.
- 8. If this is a purchase transaction and not a refinance, then attach a sales contract (the loan should go contingent upon obtaining FHA 203(k) financing).
- 9. Transfer costs shown on the last page to the Draw Request (HUD 9746-A, VMP-436).
- 10. Meaning of Abbreviations:

Each = Ea Linear foot = LF Square Foot = SF Lump Sum = LS Square Yard = SY \* = Required

M = Mandatory By HUD, R = Recommended By Consultant/Other, D = Desired By Homeowner

1. Masonry												
			Qty	Unit	Unit Cost	Total	Tax/Margin	Grand Total				
Repair Stone Foundation Wall		Material/LS	1		250.00	250.00	0.0% 0.00	\$250.00				
<b>Location</b> Le	vel R	Labor	1	Ea	0.00	0.00	Completion Hrs	s: <u> </u>				
Exterior Walls Repair damaged s	section of stucc	o at rear steps to	basem	ent, at ba	ase of wall at fr	ont patio						
Sub-Total This Section: \$250.00												
This work will be done by:: ☐ Owner ☑ Contractor ☐ Subcontractor ☐ Cost Estimate Attached: ☐ Permit Required: ☐												
Summary/Narrative Of Work To Be Done:												
Seal and monitor minor stucco cracks at walls												
3. Gutters/Downspouts												
			Qty	Unit	Unit Cost	Total	Tax/Margin	Grand Total				
Install new gutters & downspouts		Material/LS	1		1,850.00	1,850.00	0.0% 0.00	\$1,850.00				
<b>Location</b> Le	vel R	Labor	1	EA	0.00	0.00	Completion Hrs	; <u> </u>				
Roof												
Sub-Total This Section: \$1,850.00												
This work will be done by:: Owner	✓ Contracto	or Subcont	ractor		Cost Es	timate Attache	d: Permit	Required:				
Summary/Narrative Of Work To Be Done:												
		4. Roof										
			Qty	Unit	Unit Cost	Total	Tax/Margin	Grand Total				
Provide and install new roofing		Material/LS	1		5,600.00	5,600.00	0.0% 0.00	\$5,600.00				
Location	vel R	Labor	1	Ea	0.00	0.00	Completion Hrs	s: <u> </u>				
Roof Cost of roof include	des permits											
						Sub-T	otal This Section:	\$5,600.00				
This work will be done by:: Owner	✓ Contracto	or 🗌 Subcont	ractor		Cost Es	timate Attache	d: Permit	Required: 🗸				
Summary/Narrative Of Work To Be Done:  New construction:  Roof trusses placed on 2 foot cente Roof trusses placed on 16 inch cen Oriented strand board or plywood w Sheathing will be covered with 15lb. Dripedge will be applied to entire pe Self sealing asphalt shingles of own	ters will have 1/ ill be used for s felt with 3 to 6 rimeter of the ro	/2 inch or thicker heathing. inch overlaps and pof.	sheathi d felt st	apled into		ndations.						

6. Exteriors													
						Qty	Unit	Unit Cost	Total	Tax/Margin	Grand Total		
Exterior steps				Ma	aterial/LS	1		300.00	300.00	0.0% 0.00	\$300.00		
Location		Level	М		Labor	1	Ea	0.00	0.00	Completion Hr			
Exterior	Repair and a	dd handra	il to steps	front f	front porch	to yard				_			
Add handraila at atana				M	aterial/LS	1		250.00	250.00	0.0% 0.00	<b>*250.00</b>		
Add handrails at steps		Level	M				Ea	350.00 0.00	350.00 0.00		\$350.00 s: 0		
Location	Add bandrail		***	d boo		1							
Basement Add handrail and guardrail around basement stairwell enclosure- seal cracks in stairwell walls													
Sub-Total This Section: \$650.00													
This work will be done by:: ☐ Owner ☑ Contractor ☐ Subcontractor ☐ Cost Estimate Attached: ☐ Permit Required: ☐													
Summary/Narrative Of V	Vork To Be Do	ne:											
8. Driveways													
Qty Unit Unit Cost Total Tax/Margin Grand Total													
Install new asphalt driveway Material/LS							Ea	3,500.00	3,500.00	0.0% 0.00	\$3,500.00		
Location		Level	D		Labor	1	Ea	0.00	0.00	Completion Hr			
Exterior Side/s	Remove drive	way and	replace w	ith new	<i>i</i> asphalt dri	ive							
									Sub-T	otal This Section:	\$3,500.00		
				9.	Painting	g (Ext	i.)						
						Qty	Unit	Unit Cost	Total	Tax/Margin	Grand Total		
Prep and Paint all Exterior W	/ood			Ma	aterial/LS	1		250.00	250.00	0.0% 0.00	\$250.00		
Location		Level	R		Labor	1	EA	0.00	0.00	Completion Hr	S:		
Roof	Repaint defe	ctive wood	trim/barg	ge boar	rd at roof lin	e							
									Sub-T	otal This Section:	\$250.00		
This work will be done by	<u>/::</u>	ner 🗸	Contracto	or [	Subcont	ractor		Cost Es	timate Attache	ed: Permit	Required:		
Summary/Narrative Of V	Vork To Be Do	ne:											

				13. \	Window	/S					
						Qty	Unit	Unit Cost	Total	Tax/Margin	Grand Total
Install new vinyl windows				Mat	terial/LS	1		200.00	200.00	0.0% 0.00	\$200.00
Location		Level	М		Labor	1	Ea	0.00	0.00	Completion Hrs	::_0
2nd floor	Replace broke	en top sa	sh at win	ndow in fr	ont bedroo	om				•	
Repair window sash/springs				Mat	terial/LS	1		150.00	150.00	0.0% 0.00	\$150.00
Location		Level	М		Labor	1	Ea	0.00	0.00	Completion Hrs	: 0
3rd floor	Repair defect	ive sash	at 3rd flo	or bedro	om window	V					
Install new vinyl windows				Mat	terial/LS	2		250.00	500.00	0.0% 0.00	\$500.00
Location		Level	М		Labor	1	Ea	0.00	0.00	Completion Hrs	::_0
Basement	Remove rotte	d/damage	ed wood	at basem	nent windo	ws- ins	tall windo	ows to allow ver	ntilation	•	
Sub-Total This Section: \$850.00  This work will be done by:: □ Owner ☑ Contractor □ Subcontractor □ Cost Estimate Attached: □ Permit Required: □											
Summary/Narrative Of Work To Be Done:											
15. Doors (Ext.)											
Qty         Unit         Unit Cost         Total         Tax/Margin         Grand Total											
Repair exterior door Material/						1		100.00	100.00	0.0% 0.00	\$100.00
Location		Level	М		Labor	1	Ea	0.00	0.00	Completion Hrs	:0
Basement	Replace broke							0.04 50		otal This Section:	\$100.00
This work will be done by Summary/Narrative Of W			Contrac	etor	Subconti	ractor		Cost Es	timate Attache	a. Permit	Required:
				19.	Decorat	ing					
						Qty	Unit	Unit Cost	Total	Tax/Margin	Grand Total
Paint interior trim, walls and	ceilings			Mat	terial/LS	1		4,800.00	4,800.00	0.0% 0.00	\$4,800.00
Location		Level	М		Labor	1	SF	0.00	0.00	Completion Hrs	<u>:</u>
All interior rooms									Sub-T	otal This Section:	\$4,800.00
This work will be done by			Contrac	tor 🗌	Subcont	ractor		Cost Es	timate Attache	ed: Permit	Required:
Summary/Narrative Of W Paint all walls 8			requests	S.							

Any Town, USA 55555

21. Stairs												
						Qty	Unit	Unit Cost	Total	Tax/N	Iargin	Grand Total
Provide and install handrails					Material/LS	1		350.00	350.00	0.0%	0.00	\$350.00
Location		Level	М		Labor	1	Ea	0.00	0.00	Comp	letion Hrs	0
1st Floor	Provide and i	nstall prop	oer handı	ail v	with balusters a	t open	side of s	taircase to 2nd	floor			
Repair handrail/s				Г	Material/LS	1		150.00	150.00	0.0%	0.00	\$150.00
Location		Level	M		Labor	1	Ea	0.00	0.00	Comp	letion Hrs:	
Basement	Install handra	il at steps	to baser	nen	nt							
Sub-Total This Section: \$500.00												
This work will be done by:: ☐ Owner ✓ Contractor ☐ Subcontractor ☐ Cost Estimate Attached: ☐ Permit Required: ☐												
Summary/Narrative Of W	/ork To Be Do	ne:										
23. Wood Floors												
Qty Unit Unit Cost Total Tax/Margin Grand Total												
Install new hardwood floors.				Г	Material/LS	1		1,200.00	1,200.00	0.0%	0.00	\$1,200.00
Location		Level	D		Labor	1	EA	0.00	0.00		letion Hrs:	
1st Floor Remove existing flooring, install new hardwood floors at living and dining rooms												
Sub-Total This Section: \$1,200.00  This work will be done by:: □ Owner ✓ Contractor □ Subcontractor □ Cost Estimate Attached: □ Permit Required: □												
Summary/Narrative Of V	Vork To Be Do	ne:										
				25	5. Ceramio	Tile						
						Qty	Unit	Unit Cost	Total	Tax/N	Iargin	Grand Total
Install ceramic tile floor and	wainscot in ba	thtub area	for		Material/LS	1		950.00	950.00	0.0%	0.00	\$950.00
shower height.  Location		Level	R		Labor	1	EA	0.00	0.00	Comp	letion Hrs:	
Bath 1												
O				Г	3.5.4.1.105.0	_		000.00	202.00	1 0 00/	0.00	4000.00
Ceramic Floor Tile		T1	D	L	Material/LS	1	EA	800.00	800.00	0.0%	0.00	\$800.00
Location Kitchen	Replace floor	Level			Labor	1	EA	0.00	0.00	Comp	letion Hrs	
Kitchen	Replace floor	at Kitchei	1						Sub-T	otal This	Section:	\$1,750.00
This work will be done by	<u>r::</u>	ner 🗸	Contract	or	Subcont	ractor		Cost Es	timate Attache	ed: 🗌	Permit F	Required:
Summary/Narrative Of V	Vork To Be Do	ne:										

	27. Plumbing												
						Qty	Unit	Unit Cost	Total	Tax/Margi	n	Grand Tota	ı
Replace defective sewer lines	i.			M	aterial/LS	1		450.00	450.00	0.0% 0.0		\$450.0	0
Location		Level	R		Labor	1	EA	0.00	0.00	Completio	n Hrs:		_
Basement										•			
Sub-Total This Section: \$450.00													
This work will be done by:	<u>:</u>	ner 🗸	Contract	or [	Subcont	ractor		Cost Es	timate Attache	d: Pe	ermit R	tequired:	
Summary/Narrative Of W	ork To Be Do	ne:											_
28. Electrical													
						Qty	Unit	Unit Cost	Total	Tax/Margi	n	Grand Tota	ıl
Install GFCI outlet				M	aterial/LS	1		200.00	200.00	0.0% 0.0	0	\$200.0	0
Location		Level	М		Labor	1	EA	0.00	0.00	Completio	n Hrs:		
Kitchen	Rewire outlet	s at both	sides of s	ink to	correct reve	rse pol	arity situa	ation and provid	le gfi protection	1			
Install GFCI outlet				M	aterial/LS	1		100.00	100.00	0.0% 0.0	00	\$100.0	0
Location		Level	М		Labor	1	EA	0.00	0.00	Completio			
Garage Replace dead outlet at rear wall of garage with gfi protected receptacle													
Electrical Wiring			-	M	aterial/LS	1	T.4	150.00	150.00	0.0% 0.0		\$150.0	D
Location	Danies areas	Level	R		Labor	1	EA	0.00	0.00	Completio	n Hrs:		
Basement	Rewire sump	pump ou	tiet onto d	aedicat	ea circuit								
									Sub-T	otal This Sect	ion:_	\$450.00	<u>D</u>
This work will be done by:	<u>:</u>	ner 🗸	Contract	or [	Subcont	ractor		Cost Es	timate Attache	d: Pe	ermit R	tequired:	I
Summary/Narrative Of W	ork To Be Do	ne:											
				21	Cabinet	r\/							
				31.									_
				_			Unit	Unit Cost	Total	Tax/Margi		Grand Tota	
Install wood wall and base ca	binets			M	aterial/LS	1		4,000.00	4,000.00	0.0% 0.0		\$4,000.0	0
Location		Level	D		Labor	1	Ea	0.00	0.00	Completio	n Hrs:	0	
Kitchen													
Install new kitchen countertop	S			M	aterial/LS	1		1,950.00	1,950.00	0.0% 0.0	00	\$1,950.0	0
Location		Level	D		Labor	1	EA	0.00	0.00	Completio	n Hrs:		
Kitchen										•			
													_
									Sub-T	otal This Sect	ion:_	\$5,950.00	<u> </u>
This work will be done by:			Contract	or [	Subcont	ractor		Cost Es	timate Attache	d: Pe	ermit R	tequired:	ı
Summary/Narrative Of W	ork To Be Do	ne:											

#### **CONSULTANT'S COMMENT**

Construction Sub-Totals	
1. Masonry	250.00
2. Siding	0.00
3. Gutters/Downspouts	1,850.00
4. Roof	5,600.00
5. Shutters	0.00
6. Exteriors	650.00
7. Walks	0.00
8. Driveways	3,500.00
9. Painting (Ext.)	250.00
10 . Caulking	0.00
11. Fencing	0.00
12 . Grading/Landscaping	0.00
13. Windows	850.00
14. Weatherstrip	0.00
15. Doors (Ext.)	100.00
16. Doors (Int.)	0.00
17. Partition Wall	0.00
18 . Plaster/Drywall	0.00
19. Decorating	4,800.00
20. Wood Trim	0.00
21 . Stairs	500.00
22 . Closets	0.00
23. Wood Floors	1,200.00
24 . Finished Floors	0.00
25 . Ceramic Tile	1,750.00
26 . Bath Accessories	0.00
27 . Plumbing	450.00
28 . Electrical	450.00
29 . Heating	0.00
30 . Insulation	0.00
31 . Cabinetry	5,950.00
32 . Appliances	0.00
33 . Basements	0.00
34 . Cleanup	0.00
35 . Miscellaneous	0.00
Construction Cost Subtotal:	\$28,150.00

Allowable Fees & RecapTotals						
Construction Costs Subtotal : \$				28,150.00		
ALLOWABLE FEES						
Note				Fee		
Work Write Up & Consultatio	based onn repair amt			\$250.00		
Draw Fees	3 @ \$175/ea			\$150.00		
Feasibility Study	Paid by CK			\$475.00		
	Allowabl	e Fees To	tal :	\$875.00		
Contingency I		10%	_	\$2,815.00		
Grand Total: \$3				1,840.00		

All repairs must be performed in conformance with local zoning ordinances and codes. Applicant(s) and Contractor (if any) to sign and date upon final acceptance.



## **Construction Narrative**

	Inspe	ection Date:	Consultant's	S Job No: 01 Sar	nple Repor	<u>t</u>		
<u>Applicant</u>			Property Address				<u>LoanType:</u> HUD 203(k)	
			Construction Iten	n				
Consultant's	Job No: 01 S	ample Report						
			1. Masonry					
Repair Stone Fou	ındation Wall			Level: R	_ Unit:_	Ea	Completion Hrs:	0
Location:	Exterior Walls	Details: Repair dar	maged section of stucco at rear s	teps to basement, a	at base of w	all at fi	ront patio	
Owner	<b>✓</b> Contractor	Subcontractor	Seal and monitor minor stucco	cracks at walls				
			3. Gutters/Downsp	outs				
Install new gutter	rs & downspouts			Level: R	Unit:	LS	Completion Hrs:	
Location:	Roof	Details:						
Owner	<b>✓</b> Contractor	Subcontractor						
			4. Roof					
Provide and insta	all new roofing			Level: R	_ Unit:_	Ea	Completion Hrs:	0
Location:	Roof	Details: Cost of roo	of includes permits					
Owner	✓ Contractor	☐ Subcontractor	New construction: Roof trusses placed on 2 foot of Roof trusses placed on 16 inch Oriented strand board or plywo Sheathing will be covered with Dripedge will be applied to entit Self sealing asphalt shingles of recommendations.	centers will have 1, od will be used for s 15lb. felt with 3 to 6 re perimeter of the r	/2 inch or the sheathing. Inch overla roof.	icker s ps and	heathing I felt stapled into plac	e.
			6. Exteriors					
Exterior steps				Level: M	Unit:_	LS	Completion Hrs:	0
Location:	Exterior	Details: Repair and	d add handrail to steps front front	porch to yard				
Add handrails at	steps			Level: M	Unit:	EA	Completion Hrs:	0
Location:	Basement	Details: Add handr	ail and guardrail around baseme	nt stairwell enclosur	re- seal crac	ks in s	stairwell walls	
Owner	<b>✓</b> Contractor	Subcontractor						
			8. Driveways					
Install new aspha	alt driveway			Level: D	Unit:_	Ea	Completion Hrs:	0
Location:	Exterior Side/s	Details: Remove d	riveway and replace with new as	phalt drive				
Owner	Contractor	Subcontractor						

Consultant's Job No: 01 Sample Report 9. Painting (Ext.) Prep and Paint all Exterior Wood Level: R Unit: LS **Completion Hrs:** Details: Repaint defective wood trim/barge board at roof line Location: Roof Owner **✓** Contractor Subcontractor 13. Windows Install new vinyl windows Level: M Unit: EA **Completion Hrs:** Details: Replace broken top sash at window in front bedroom Location: 2nd floor Repair window sash/springs Level: M Unit: Ea **Completion Hrs:** Details: Repair defective sash at 3rd floor bedroom window Location: 3rd floor Install new vinyl windows Level: M Unit: EA **Completion Hrs:** Location: Basement Details: Remove rotted/damaged wood at basement windows- install windows to allow ventilation Owner **✓** Contractor Subcontractor 15. Doors (Ext.) Repair exterior door Level: M Unit: Ea **Completion Hrs:** Details: Replace broken window in basement door Location: **Basement** Owner **✓** Contractor Subcontractor 19. Decorating Paint interior trim, walls and ceilings M Unit: LS **Completion Hrs:** Level: **Location: All interior rooms Details:** Paint all walls & ceiling to homeowners requests. Subcontractor Owner **✓** Contractor 21. Stairs Provide and install handrails **Completion Hrs:** Level: M Unit: LS Location: 1st Floor Details: Provide and install proper handrail with balusters at open side of staircase to 2nd floor Repair handrail/s **Completion Hrs:** Level: M Unit: Ea Details: Install handrail at steps to basement Location: **Basement** Owner **✓** Contractor Subcontractor 23. Wood Floors Install new hardwood floors. Level: Unit: LS **Completion Hrs:** Location: 1st Floor Details: Remove existing flooring, install new hardwood floors at living and dining rooms Owner ✓ Contractor Subcontractor 25. Ceramic Tile

R

D

Level:

Level:

Unit: LS

Unit: LS

Lavale: M. Mandatory Ry HIID	P. Pacommended by Consultant	D. Decired By Owner

Install ceramic tile floor and wainscot in bathtub area for shower height.

**Details:** 

Subcontractor

Details: Replace floor at kitchen

Bath 1

Kitchen

**✓** Contractor

**Completion Hrs:** 

**Completion Hrs:** 

Location:

Location:

Ceramic Floor Tile

Owner

Consultant's Job No: 01 Sample Report

	27. Plumbing			
Replace defective sewer lines.		Level: R	Unit: LS	Completion Hrs:
Location: Basement	Details:			
Owner Contractor	Subcontractor			
	28. Electrical			
Install GFCI outlet		Level: M	Unit: <u>EA</u>	Completion Hrs:
Location: Kitchen	Details: Rewire outlets at both sides of sink to correct	reverse polarity situa	ation and provid	e gfi protection
Install GFCI outlet		Level: M_	Unit: EA	Completion Hrs:
Location: Garage	Details: Replace dead outlet at rear wall of garage with	h gfi protected recep	otacle	
<b>Electrical Wiring</b>		Level: R	Unit: LS	Completion Hrs:
Location: Basement	Details: Rewire sump pump outlet onto dedicated circu	uit		
Owner Contractor	Subcontractor			
	31. Cabinetry			
Install wood wall and base cabinets		Level: D	Unit: LS	Completion Hrs: 0
Location: Kitchen	Details:			
Install new kitchen countertops		Level:D	Unit: LS	Completion Hrs:
Location: Kitchen	Details:			
Owner Contractor	Subcontractor			

### **Narrative Totals**

#### **Construction Item Totals**

1. Masonry	250.00
2. Siding	0.00
3. Gutters/Downspouts	1,850.00
4. Roof	5,600.00
5. Shutters	0.00
6. Exteriors	650.00
7. Walks	0.00
8. Driveways	3,500.00
9. Painting (Ext.)	250.00
10. Caulking	0.00
11. Fencing	0.00
12. Grading/Landscaping	0.00
13. Windows	850.00
14. Weatherstrip	0.00
15. Doors (Ext.)	100.00
16. Doors (Int.)	0.00
17. Partition Wall	0.00
18 . Plaster/Drywall	0.00
19. Decorating	4,800.00
20 . Wood Trim	0.00
21 . Stairs	500.00
22. Closets	0.00
23. Wood Floors	1,200.00
24. Finished Floors	0.00
25 . Ceramic Tile	1,750.00
26. Bath Accessories	0.00
27. Plumbing	450.00
28. Electrical	450.00
29. Heating	0.00
30 . Insulation	0.00
31. Cabinetry	5,950.00
32. Appliances	0.00
33. Basements	0.00
34. Cleanup	0.00
35 . Miscellaneous	0.00
Construction Cost Subtotal:	\$28,150.00

#### **Allowable Fees & Recap Totals**

Construction (	\$2	28,150.00			
ALLOV	ALLOWABLE FEES				
	Note				
Work Write Up & Consultati	based onn repair amt			\$250.00	
Draw Fees	3 @ \$175/ea			\$150.00	
Feasibility Study	Paid by CK			\$475.00	
	Allowable Fees Total :				
Contingency	Reserve:	10%		\$2,815.00	
Grand Total:				31,840.00	

Borrower's Acceptance:	Date:	
bullumer s Acceptance.	Datc.	

# Final Work Write Up Summary Value Home Inspections, Inc.

(215) 886-0010

#### **Applicant/Property Address**

#### **Lender & Loan Number**

FHA Case Number

**Inspector & ID Number** 

Sample Home Mortgage

			Materials		Tax or			Completion	1	
	Construction Item	Labor	or Lump Sum	Total	Margin %	Tax/Margin	Grand Total	Hours	Draw Number	Draw Total
1.	Masonry	0.00	250.00	250.00	0.00%	0.00	250.00	0.0		
2.	Siding	0.00	0.00	0.00				0.0		
3.	Gutters/Downspouts	0.00	1,850.00	1,850.00	0.00%	0.00	1,850.00			
4.	Roof	0.00	5,600.00	5,600.00	0.00%	0.00	5,600.00	0.0		
5.	Shutters	0.00	0.00	0.00	0.00%	0.00		0.0		
6.	Exteriors	0.00	650.00	650.00	0.00%	0.00	650.00	0.0		
7.	Walks	0.00	0.00	0.00	0.00%	0.00		0.0		
8.	Driveways	0.00	3,500.00	3,500.00	0.00%	0.00	3,500.00	0.0		
9.	Painting (Ext.)	0.00	250.00	250.00	0.00%	0.00	250.00			
10.	Caulking	0.00	0.00	0.00	0.00%	0.00		0.0		
11.	Fencing	0.00	0.00	0.00	0.00%	0.00		0.0		
12.	Grading/Landscaping	0.00	0.00	0.00	0.00%	0.00		0.0		
13.	Windows	0.00	850.00	850.00	0.00%	0.00	850.00	0.0		
14.	Weatherstrip	0.00	0.00	0.00	0.00%	0.00		0.0		
15.	Doors (Ext.)	0.00	100.00	100.00	0.00%	0.00	100.00	0.0		
16.	Doors (Int.)	0.00	0.00	0.00	0.00%	0.00		0.0		
17.	Partition Wall	0.00	0.00	0.00	0.00%	0.00		0.0		
18.	Plaster/Drywall	0.00	0.00	0.00	0.00%	0.00		0.0		
19.	Decorating	0.00	4,800.00	4,800.00	0.00%	0.00	4,800.00			
20.	Wood Trim	0.00	0.00	0.00	0.00%	0.00		0.0		
21.	Stairs	0.00	500.00	500.00	0.00%	0.00	500.00	0.0		
22.	Closets	0.00	0.00	0.00	0.00%	0.00		0.0		
23.	Wood Floors	0.00	1,200.00	1,200.00	0.00%	0.00	1,200.00			
24.	Finished Floors	0.00	0.00	0.00	0.00%	0.00		0.0		
25.	Ceramic Tile	0.00	1,750.00	1,750.00	0.00%	0.00	1,750.00			
26.	Bath Accessories	0.00	0.00	0.00	0.00%	0.00		0.0		
27.	Plumbing	0.00	450.00	450.00	0.00%	0.00	450.00			
28.	Electrical	0.00	450.00	450.00	0.00%	0.00	450.00			
29.	Heating	0.00	0.00	0.00	0.00%	0.00		0.0		
30.	Insulation	0.00	0.00	0.00	0.00%	0.00		0.0		
31.	Cabinetry	0.00	5,950.00	5,950.00	0.00%	0.00	5,950.00	0.0		
32.	Appliances	0.00	0.00	0.00	0.00%	0.00		0.0		
33.	Basements	0.00	0.00	0.00	0.00%	0.00		0.0		
34.	Cleanup	0.00	0.00	0.00	0.00%	0.00		0.0		
35.	Miscellaneous	0.00	0.00	0.00	0.00%	0.00		0.0		
10	0% Contingency Reserve:	\$2,815.00 +	Total Estimate:	\$28,150.00	_ =	Total Loan Estimate :	\$30,965.00		Draw Request Subtotal:	

**Total Completion Hours:** 



# **Consultant's Identity-Of-Interest Certification**

Borrower's Name(s)	
Property Address	
FHA Case No.	
"I hereby certify that I have carefully inspected this property for compliance with the ghealth and safety) in Handbook 4905.1. I have required as neccessary and reviewed applicable engineering and termite reports, and the estimated rehabilitation cost and property. I have no personal interest, present or prospective, in this property, applicate that I have no identity-of-interest or conflict-of interest with the borrower, seller, lender subcontractor. To the best of my knowledge, I have reported all items requiring correct meets all HUD requirements for Rehabilitation Mortgage Insurance."  Warning: HUD will prosecute false claims and statements. Conviction may result	the architectural exhibits, including any they are acceptable for the rehabilitation of the nt or proceeds of the mortgage. I also certify r, realtor, appraiser, plan reviewer, contractor or ction and that the rehabilitation proposal now
(18 U.S.C. 1001, 1010, 1012; 31 U.S.C 3729, 3802).	
	Date:
Consultant/Plan Reviewer's Signature:	
Consultant: Catherine Hall	

#### **Draw Request**

#### U.S. Department of Housing and **Urban Development**

OMB Approval No. 2502-0527 (exp. 04/30/2011)

**HUD 203(k)** Office of Housing

Public reporting burden for this collection of information is estimated to average I hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This agency may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number.

This information collection involves an expanded information requirement for lenders that originate and service Section 203(k) mortgages. The purpose of the information is to help mitigate program abuses. The expanded information focuses on the loan origination process and requires increased documentation and strengthened internal control procedures. Periodic reporting of the information is not required. The information also includes information that was voluntarily accepted by the 203(k) lending community. The information provides a more comprehensive basis for evaluating lender underwriting practices and thereby improves risk management of the 203(k) loan portfolio. Responses are required to obtain benefits under Section 203(k) of the National Housing Act (12 U.S.C. 1703). No assurance of confidentiality is provided.

Borower's Name & Property Address	Lender's Name & Address	FHA Case Number	
	Sample Home Mortgage		
	5555 Any Street Any Town, USA 55555	This Draw Number Initial	Date

I certify that I have carefully inspected this property for compliance with the general acceptability requirements (including health and safety) in Handbook 4905.1. I have reviewed the attached architectural exhibits and the estimated rehabilitation costs listed in column 1 below; they are acceptable for the rehabilitation of this property. I have no personal interest, present or prospective, in the property, applicant, or proceeds of the mortgage. To the best of my knowledge, I have reported all items requiring correction and that the rehabilitation proposal now meets all HUD requirements for 203(k) Rehabilitation Mortgage Insurance.

#### **HUD-Accepted Consultant / Plan Reviewer's Signature & Date**

Suggested Contingency Reserve Amount

X						\$2,81	5.00	10%	%
			Tota	al Cost of Re	habilitation		Inspector/Lender		
	Construction Item	Total Escrow Col. 1	Previous Draw Totals  Col. 2	%	Request for This Draw Col. 3	%	Adusted Amounts Col. 4	%	
1.	Masonry	\$250.00							1.
2.	Siding	\$0.00							2.
3.	Gutters/Downspouts	\$1,850.00							3.
4 .	Roof	\$5,600.00							4.
5.	Shutters	\$0.00							5.
6.	Exteriors	\$650.00							6.
7.	Walks	\$0.00							7.
8.	Driveways	\$3,500.00							8.
9.	Painting (Ext.)	\$250.00							9.
10.	Caulking	\$0.00							10.
11.	Fencing	\$0.00							11 .
12.	Grading/Landscaping	\$0.00							12.
13.	Windows	\$850.00							13.
14.	Weatherstrip	\$0.00							14.
15.	Doors (Ext.)	\$100.00							15.
16.	Doors (Int.)	\$0.00							16.
17.	Partition Wall	\$0.00							17.
18.	Plaster/Drywall	\$0.00							18.
19.	Decorating	\$4,800.00							19.
20 .	Wood Trim	\$0.00							20 .
21.	Stairs	\$500.00							21 .
22.	Closets	\$0.00							22 .
23 .	Wood Floors	\$1,200.00							23 .
24 .	Finished Floors	\$0.00							24 .
25 .	Ceramic Tile	\$1,750.00							25 .
26.	Bath Accessories	\$0.00							26.
27 .	Plumbing	\$450.00							27 .
28 .	Electrical	\$450.00							28 .
29 .	Heating	\$0.00							29 .
30 .	Insulation	\$0.00							30 .
31.	Cabinetry	\$5,950.00							31 .
32 .	Appliances	\$0.00							32 .
33 .	Basements	\$0.00							33 .
34 .	Cleanup	\$0.00							34 .
35 .	Miscellaneous	\$0.00							35 .
36.	Totals	\$28,150.00							36.

rehabilitation as shown above in column 3. I understand that I cannot obtain additional monies from the rehabilitation account without the approval of the lender. I also understand that a 10% holdback will not be released until all work is complete and it is determined that no mechanic's and materialmen's liens have been placed on the property. After the final inspection, the monies in escrow account will be distributed as required by the 203(k) program procedures. **Borrower's Signature** ✓ Owner-Occupied Investor-Builder  $\mathbf{X}$ This draw request is submitted for payment. All completed work has been done in a workmanlike manner. I understand that a 10% holdback will not be released until all work is completed and it is determined that no mechanic's and materialmen's liens have been placed on the property. (If any) X **General Contractor's Signature** I certify that I have carefully inspected this property on this date. The draw amounts are acceptable except as modified in column 4. I further certify that I have not accepted any work that is not yet completed in a workmanlike manner and I recommend that the rehabilitation escrow funds be released for the completed work. Inspector's Signature X I.D. Number The Lender is herby authorized to release the following funds from the escrow account. Approved for Release This Draw Totals to Date Total from Above Payable to the Borrower Payable to the Fee Inspector \$ Less 10% Holdback Payable To \$ \$ \$ Net Amount Due Borrower \$ \$ Signiture & Date Lender-Authorized Agent X DE Underwriter Lender Holding Rehabilitation Escrow Account (name, address, & phone number) Originating Lender Sill Retains Funds Rehab Funds Transfered to: FHA Case Number **Rehabilitation Inspection Report** I. Inspection of On-Site Repairs and/or Improvements Reveals: 1. 3. No noncompliance observed. Unable To Make Inspection. (explained Below) 2. Correction essential as explained below. 4 Acceptable variations as described below. 5. On-site improvements acceptably completed. Will examine at next inspection. h. Do not conceal until reinspected. II. Explanation of statements checked above. Inspection Number Draw Other (explain) Contingency Reserve Final Change Inspection Inspection Order Inspection No. No. Certification: I certify that I have carefully inspected this property on this date. I have no personal interest, present or prospective, in the property, applicant, or proceeds of the mortgage. To the best of my knowledge, I have reported all noncompliance, work requiring correction, and unacceptable work. I also certify that this Draw Request is for completed work and I have not accepted any work that is not properly installed in a workmanlike Inspector Fee **ID Number** Signature & Date Consultant/Inspector Fee Inspector P0437 DE Staff Inspector

I hereby certify that all the information stated herein, as well as any information provided in the accompaniment herewith, is true and accurate. Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties.(18 U.S.C. 1001,1012;31 U.S.C.

This draw request is submitted for payment. All completed work has been done in a workmanlike manner. I hereby certify to the actual cost of

3729.3802)



## **Consultant's Allowable Fee Agreement**

repared for:		Address:			
Lender: Sample Home Mort	gage	Loan Originator:	L	oan Type:	HUD 203(k)
This agreement is entered	l on	, between Catherine Hall	(CONSULTAN	Γ) and	
	(BUYER) regarding th	ne subject property:			
For the sum(s) specific	ed the CONSULTANT agre	es to:			
inspect the p 203(k) Rehat services. This continue the determined q	nysical property, identify an ilitation Mortgage Program fee will be fully credited to application process. This fe uickly that the needed repa	ver(s)' Agent(s) and/or Contracteas in need of improvement, and a feasibility fee will be due and another the Total Consultant Feede is non-contingent and non-realirs are unfeasible for the Borroe Inspection and no additional page 1	nd determine ownd payable upon (below) should befundable. If upon wer(s) and/or e	verall suitable completion Borrower(son initial exacts and initial exacts are solved by the complete and initial exacts are solved by the complete are solve	ility for FHA's n of these s) decide to amination it is expensive, the
would be rec	ommended to be done at the	ill list work items that: A) must his time by the Consultant or ot s) will jointly determine the sco	hers, and; C) ar		
architectural		n a HUD accepted format, with ified architectural drawings. If somer.			
service (whic		ower(s) agrees to pay Consulta em #1 above) which is based o wer at closing.			
contractors agreed to addition to the above of schedule the additiona and will be due and pa	by both the Consultant and Consultant fee. The Consultant fee. The Consult testing for the borrower(s yable at the time of service		arges for these a charges in adv e the sole respo	testing ser vance (see onsibility of	vices are in below), and may
Additional Testing Ser		may be necessary and their es	timated charges	<u>3:</u>	
		owable Fee Items			
	Allowable Fee Item w Fees	Fee Item Note 3 @ \$350/ea		Fee	
	sibility Study	Paid by CK		\$350.00 \$475.00	
1 60	isibility Study		Be Paid:	\$625.00	
ander's assurance of r	avment for halance du	ue is acceptable with Sign		`	
•	ayment for Dalance Ut	io io acceptable with olyl	iatui e (DeiOW	<i>)</i> -	
K f guaranteeing payment. S	signature of Authorized Off	Date: icial of the Lender			
<	_	Date:			
Sorrower:		Date			
		Date:			
(		י מזכו			

#### **Homeowner/Contractor Agreement**

Borrower's Name(s):	Contractor's Name:				
Address:	Address: #Error				
Telephone Number:	Phone Number:				
FHA Case No.	License No.:				
THIS AGREEMENT, made this date,					
<b>4. Subcontractor:</b> Selected by the contractor, except that the contractor will not employ any subcontractor to whom the owner may have a reasonable objection, nor will the contractor be required by the owner to employ any subcontractor to whom the contractor has a reasonable objection.					
<b>5. Work By Owner or Other Contractor:</b> The owner reserves the right to perform work related to the project, but which is not a part of this Agreement, and to award separate contracts in connection with other portions of the project not detailed in this Agreement. All contractors and subcontractors will be afforded reasonable opportunity for the storage of materials and equipment by the owner and by each other. Any costs arising by defective or ill-timed work will be borne by the responsible party.					
<b>6. Binding Arbitration:</b> Claims or disputes relating to the Agreement or General Provisions will be resolved by the Construction Industry Arbitration Rules of the American Arbitration Association (AAA) unless both parties mutually agree to other methods. The notice of the demand for arbitration must be filed in writing with the other party to this Agreement and with the AAA and must be made in a reasonable time after the dispute has arisen. The award rendered by the arbitrator(s) will be considered final and judgment may be entered upon it in accordance with applicable law in any court having jurisdiction thereof.					
Borrower's Initial:	Contractor's Initail:				

- 7. Cleanup and Trash Removal: The contractor will keep the owner's residence free from waste or rubbish resulting from the work. All waste, rubbish, tools, construction materials, and machinery will be removed promptly after completion of the work by the contractor.
- **8. Time:** With respect to the scheduled completion of the work, time is of the essence. If the contractor is delayed at anytime in the progress of the work by change orders, fire, labor disputes, acts of God or other causes beyond the contractor's control, the completion schedule for the work or affected parts of the work may be extended by the same amount of time caused by the delay. The contractor must begin work no later than 30 days after loan dosing and will not cease work for more than 30 consecutive days.
- 9. Payments and Completion: Payments may be withheld because of. (1) defective work not remedied; (2) failure of contractor to make proper payments to subcontractors, workers, or suppliers; (3) persistent failure to carry out work in accordance with this Agreement or these general conditions, or (4) legal claims. Final payment will be due after complete release of any and all liens arising out of the contract or submission of receipts or other evidence of payment covering all subcontractors or suppliers who could file such a lien. The contractor agrees to indemnify the Owner against such liens and will refund all monies including costs and reasonable attorney's fees paid by the owner in discharging the liens. A 10 percent holdback is required by the lender to assure the work has been properly completed and there are no liens on the property.
- 10. Protection of Property and Persons: The contractor is responsible for initiating, maintaining, and supervising all necessary or required safety programs. The contractor must comply with all applicable laws, regulations, ordinances, orders or laws of federal, state, county or local governments. The contractor will indemnify the owner for all property loss or damage to the owner caused by his/her employees or his/her direct or subtier subcontractors.
- 11. Insurance: The contractor will purchase and maintain such insurance necessary to protect from claims under workers compensation and from any damage to the owner(s) property resulting from the conduct of this contract.
- 12. Changes in the Contract: The owner may order changes, additions or modifications (using form HUD-92577) without invalidating the contract. Such changes must be in writing and signed by the owner and accepted by the lender. Not all change order requests may be accepted by the lender, therefore, the contractor proceeds at his/her own risk if work is completed without an accepted change order.
- **13. Correction of Deficiencies:** The contractor must correct promptly any work of his/her own or his/her subcontractors found to be defective or not complying with the terms of the contract.
- **14. Warranty:** The contractor will provide a one-year warranty on all labor and materials used in the rehabilitation of the property. This warranty must extend one year from the date of completion of the contract or longer if prescribed by law unless otherwise specified by other terms of this contract. Disputes will be resolved through the Construction Industry Arbitration Rules of the American Arbitration Association.
- **I5. Termination:** If the owner fails to make a payment under the terms of this Agreement, through no fault of the contractor, the contractor may, upon ten working days written notice to the owner, and if not satisfied, terminate this Agreement. The owner will be responsible for paying the contractor for all work completed.

If the contractor fails or neglects to carry out the terms of the contract, the owner, after ten working days written notice to the contractor, may terminate this Agreement.

Owner Signature(s) And Date	Owner Signature(s) And Date	
Owner Signature(s) And Date	Owner Signature(s) And Date	
	Contractor's Signature(s) And Date	



## **Certification Letter**

HUD 203(k)

Date:					
Buyer's Name:					
Address:					
Phone Number:					
FHA Case Number:					
I hereby certify that I have car	efully inspected the following pro	perty at:			
for compliance with the generation or its successors.	al acceptability requirements (inc	luding health and safety) in Handbook 4905.1			
I have reviewed the attached a have determined them to be a		mated rehabilitation costs of this property, and			
I have no personal interest, pr	esent or prospective, in the prope	erty, applicant, or proceeds of the mortgage.			
To the best of my knowledge I have reported all items requiring correction and that the rehabilitation proposal now meets all HUD requirements for 203(k) Rehabilitation Mortgage Insurance (Handbook 4240.4 or its successors).					
	X	Date:			
	HUD Consultant:				
	ID Number:				